


↑ FRAGILE ↑
↑ 7 FT. TURBO ↑

↑ FRAGILE ↑
7 FT. TURBO HOCKEY
CAUTION HEAVY ITEM

THIS SIDE UP



Beginning plans.
Spare tire clearance was required.



Purchase a service part only.
\$30 at a local bike shop.



2" tube steel was used. Gusset was added for strength. Extra rod added to prevent the bike from swinging (covered in red hose).



Service part fit easily on frame. Only 2 holes were needed to fasten the head to the frame.